Work	Order	ID	61532
------	-------	----	-------



Page 1

Monday. August 30, 2010 10:19:21 AM Item ID: D3861-041 Accept Setup Start Revision ID: Stop Item Name: Wearplate Start Otv: 4.00 Start Date: 8/30/2010 **Cust Item ID:** Req'd Qty: 4.00 Required Date: 9/6/2010 Customer: Reference: Run Start Date: 10-8-30 Tooling: Process Plan: **Approvals:** Date: Stop Date: SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Tool ID Reject Tool # Plan Accept Reject Insp. Work Center ID **Description** Run Hours Code Qty **Qty** Number Stamp Draw Nbr **Revision Nbr** D3861 Plo 3 100 0:00 FLOW WATER JET B10-9-7 Wateriet 0.00 Memo FLOW CNC Wateriet 1-Cut as per Dwg D3861 □Dwg Rev: □Prog Rev: A □2-304.063 Deburr if necessary 110 QC2- Inspect parts off machine FAI/FAIB 0.00 1B10-9-7 OC 0.00 Memo Quality Control 120 QC8- Inspect parts - second check Sidorloz 0.00 Memo Quality Control

Dart Aerospace Ltd	Dart	Aer	osp	ace	Ltd
--------------------	------	-----	-----	-----	-----

W/0:6	/532	WORK ORDER CI	HANGES				
DATE	STEP	Pern. Jonse.	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Wodla	11	ADD Day # + Rev 10 Leader him	Δ	10,09.16			Solator
					,		

Part No: <u>D3861-041</u> PAR #: _	Fault Category:	NCR: Yes No DQA:	Date:
Resolution:	Disposition:	QA: N/C Closed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NC	Secription of NC Corrective Action Section B			Verification	Approval		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	Approval QC Inspector	
						** *			
					,				

Work Order ID 61532

Monday, August 30, 2010 10:19:21 AM



Page 2

Item ID:

D3861-041

Accept

Setup Start



Revision ID:

Start Date:

Item Name:

Required Date: 9/6/2010

Wearplate

8/30/2010

Start Otv: 4.00

Reg'd Oty: 4.00



Cust Item ID:

Customer:

Tool ID

Reference:

Approvals:

Process Plan: Date:

Tooling:

0.00

SPC (Y/N):

Set Up/

Run Hours

Date:

Date:

Tool # Plan

Code

Run

Reject

P- 10-9-15

Qty

Start Stop

Reject

Number

Stop



Insp.

Stamp

Sequence ID/

Work Center ID

130

Large Fab Large Fab

Large Fab

Operation

Description

Memo

QC: Date:

0.00

1-Weld D3009-3 cups as per dwg D3861□ A/R 316L stainless steel rod 2059B Hard Coat rod Batch: M 1/5553

DT9463 for welding*****

OC9- Inspect visual per OSI004- Fusion Welds

140

Quality Control

Memo

Memo

0.00 0.00

Accept

Qty

150

Quality Control

QC5- Inspect part completeness to step on W/O

W/O:			WC	RK ORDER CHANC	GES						
DATE	STEP	PROCEDURE CHANGE			E	Зу	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
		PAR #:	Fault Cate	Fault Category: NCR: Yes No D				DQA: Date:			
	Res	solution:	Disposition	າ:	QA: N	/C Clos	sed:		Date: _		
NCR:			WORK ORDI	ER NON-CONFORM	ANCE (NCR)	· · ·	- ·			
DATE	STEP	Description of NC		Corrective Action Section B			Verific			Approval	
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section	on C	Chief Eng	QC Inspector	
									:		
							:				
						·-·		; 			
								:			
								į			
								;			

Work Order ID 61532

Monday, August 30, 2010 10:19:21 AM



Page 3

Item ID:

D3861-041

Accept



Setup Start

Stop



Revision ID:

Item Name: Wearplate

Start Date:

Start Otv: 4.00 8/30/2010

Required Date: 9/6/2010

Reg'd Otv: 4.00



Date:

Cust Item ID: Customer:

Tool ID

-) M 10/09/15

Reference:

Approvals:	s:	Approva	
------------	----	----------------	--

Process Plan: OC:

Operation

Description

Date:

Tooling:

0.00

SPC (Y/N):

Set Up/

Run Hours

Date: Date:

Tool # Plan

Code

Run

Accept

Qty

Stop

Reject

Qty

Start



Number Stamp

Insp.

Reject

Sequence ID/

Work Center ID

160

Powdercoat Powder Coating Memo

11/112588

Grey Sandtex(Ref:4.3.5.6) per QSI005 4.3

0.00

Identify as per dwg & Stock Location: 500

3:1500 OFINISH TIME:

2:450m OVEN TEMPERATURE: START TIME:

170

QC

Quality Control

QC3- Inspect Part Finish

0.00

Memo

0.00

180

Packaging

Memo

0.00

0.00

Packaging

	•									
W/O:			WO	RK ORDER CHANG	GES					
DATE	STEP	PR	ROCEDURE CHANGE By			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
							į			
~										
Part No	•	DAD #-	Foult Cotos		NCD: Voc	No DO		Data		
raitivo		PAR #:					ed: Date:			
NCR:				R NON-CONFORM				Date		
NON.			Corrective Action Continue							
DATE	STEP Description of NC Section A		Initial Chief Eng	Action Description Chief Eng	Sign & Date		Verification Section C	Approval Chief Eng	Approval QC Inspector	
					,					

Work Order ID 61532

Monday, August 30, 2010 10:19:21 AM



Page 4

Item ID:

D3861-041

Accept



Setup Start



Revision ID:

Start Date:

Item Name: Wearplate

Required Date: 9/6/2010

8/30/2010

Start Qty: 4.00

Operation

Description

Req'd Qty: 4.00

Cust Item ID:

Customer:

Reference:

Δ	nn	rova	le•
Δ	บบ	rova	15:

Process Plan:

Date:

Tooling:

Date:

Run Start

QC:

Date:____

SPC (Y/N):

Date:

Stop

Stop

Sequence ID/

Work Center ID

QC21- Final Inspection - Work Order Release

Set Up/ **Run Hours** **Tool ID**

Tool # Plan Accept Qty Code

Reject Qty

Reject Insp. Number Stamp

190

Memo

0.00

0.00

Quality Control

10 09 16 110-914 (4)

Dart .	Aer	osr	oace	Ltd
--------	-----	-----	------	-----

W/O:			W	ORK ORDER CHANG	ES					
DATE	STEP	PRO	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					,					
Part No										
	Res	solution:	Dispositio	n:	QA	N/C Clo	sed:		Date:	
NCR:			WORK ORD	ER NON-CONFORM	ANCE	(NCR				
DATE	STEP	STEP Description of NC Section A	Corrective Action Section Initial Action Description			Sign & Verific			fication Approval Chief Eng	
			Chief Eng	Chief Eng		Date		:		QC Inspector
									<u> </u>	
					:					

Picklist Print

Monday, August 30, 2010 10:19:26 AM

Work Order ID: 61532

Parent Item:

D3861-041

Parent Item Name: Wearplate



Start Date: 8/30/2010

Required Date: 9/6/2010

Page 1

Start Qty: 4.00

Required Oty: 4.00

α.					
L0	m	m	en	ts:	

IPP Rev:A 09-02-03 new issue DD verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M304S16GA	WK 755 0 (0) 7 55	Purchased	No			100	sf	82.9000	1.09	4.36 LD	.10-9-	7	
				Location MAT20	115440	Loc	Oty 82.9 82.9	Loc Code	- 1	(5440	-	9	
D3009-3		Manufactured	No			130	Each	257.0000		24 EL	10	o-9,	14
•				<u>Location</u> WA		Loc	Oty 257	Loc Code					
				WA	42377		257 257			24			

W/O:			WO	RK ORDER CHANG	ES							
DATE	STEP	PR	OCEDURE CHAN		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
·												
Part No: PAR #: _			Fault Category:			NCR: Yes No DQA: Date:						
	Res	olution:	Disposition	:	QA: N/C (Closed:		Date: _				
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NC	R)						
DATE	STEP	Description of NC			tion B	Verific	cation	Approval	Approval			
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date		ion C	Chief Eng	QC Inspector			

DART AEROSPACE LTD	Work Order:	61532
Description: Wearplate	Part Number:	D3861-1
Inspection Dwg: D3861 Rev: A		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Ø0.879	+0.010/-0.001	.878	>		N 1809	
1.70	+/-0.030	1,707	000		V	
5.000	+/-0.010	4.994	>		V	
6.5	+/-0.030	6.507			V	
1.50	+/-0.030	1.503	X		V	
9.750	+/-0.010	9,750	*		7 301	
11.000	+/-0.010	11.00	7		7	
23.20	+/-0.030	93.30	&		7	
0.063	+/-0.010	,059	×		V	
						· · · · · · · · · · · · · · · · · · ·
				1		


Measured by:	B	Audited by:	Preliminary Approval:	
Date:	10-9-7	Date: 10/09/07	Date:]

Rev	Date	Change		Revised by	
Α	10.06.07	New Issue	P/O D 3861-041	KJ OX	- \ \
				1/1	- Po-


Dart Aerospace Lt

	•								
W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PR	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	A :	_ Date: _	
Resolution: Disposition: QA: N/C Closed:						Date: _			
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NCR)			
DATE	STEP	Description of NC		on B	Verific	erification Approval		Approval	
	OIL!	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC Inspector
	ļ								
}									
							····		`
						į			
									}
									,

[·] H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE



W/O:			W	ORK ORDER CHANG	SES					
DATE	STEP	PRO	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									5	
										
						3				
Part No	•	PAR #:	Fault Cate	egory:	NCR	: Yes I	No DQ	A:	Date:	
	Re	esolution:	Disposition	on:	QA:	N/C Clo	sed:		Date: _	
NCR:		1	WORK ORE	DER NON-CONFORM	ANCE	(NCR				
DATE	STEP	Description of NC		tion B	Verification		Approval	Approval		
	O.L.	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section	on C	Chief Eng	QC Inspector
i										
						10				
								!		
			1 1		1]	ŀ



W/O:			WO	RK ORDER CHANG	GES		.,		·
DATE	STEP	PR	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
									·
									2
Part No	:	PAR #:	Fault Categ	jory:	NCR: Yes	No DQ	A:	Date:	
Resolution:			Disposition	QA: N/C (QA: N/C Closed: Date:				
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NC	R)			
DATE	OTED	Description of NC		Corrective Action Sec	ction B	Verifi	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sect	ion C	Chief Eng	QC Inspector
							- 4		